

Allen-Bradley PowerFlex 700 VC Series A

Engineering Release Notes and Firmware Update Instructions

April 8, 2003

UPDATE CAN BE APPLIED TO:

Product Catalog #	20B (Vector Control Option)
Description	PowerFlex 700 VC Vector Control Drive
Firmware	1.001 or later

REVISION INFORMATION AFTER UPDATE IS APPLIED:

Product Revision	2.003
Application Program Firmware Revision	2.003.35
Boot Program Firmware Revision	1.001.23



Once a flash update has been started, do not remove power from the drive until after the download has completed and the Drive has reset. If power is removed during Application Flash, the drive will remain in Boot and can be reflashed.

HyperTerminal UPDATE INSTRUCTIONS:

Use HyperTerminal to load the following files in the order listed:

1. PF700VC_2_003_35_App.bin

ControlFLASH & DriveExplorer Flash UPDATE INSTRUCTIONS:

Install and apply the ControlFLASH kit named:

1. PF700VC_2_003_35_Update.exe