

0 - 10 Volt Speed Command

Parameters that need to be reprogrammed
 P038 [speed Reference] = 2 "0-10V Input"

