

# Remote Potentiometer

Parameters that need to be reprogrammed

P038 [Speed Reference] = 2 "0-10V Input"

1-10K Ohm Pot.  
Recommended  
2 Watt minimum

