



Firmware Release Notes

ControlLogix Drive Module (v2.03)

(Cat. No. 1756-DMD30)

These release notes correspond to major revision 2, minor revision 3 of the SD3000 Interface (1756-DMD30) firmware. Use this firmware release with:

Software Product:	Compatible Version:
RSLogix 5000 programming software	8.02.00 or later
RSLinx software	2.30 or later
RSNetWorx for ControlNet software	3.00 or later
DriveExecutive programming software	1.01 or later

Corrected Anomaly

This revision corrects an anomaly with the handling of the “User Defined Text” field. Text entered into this field (via the Properties Dialog Box within DriveExecutive), was not being written correctly to the drive module, resulting in the loss of the text and the occasional resetting of the drive module parameters to their default values.

Firmware Revision History

Refer to the following publications to understand changes made in each firmware revision:

This publication describes
1756-RN580	the initial release of revision 1.09
1756-RN585	the changes from revision 1.09 to 1.16
1756-RN589	the changes from revision 1.16 to 1.19
1756-RN593	the changes from revision 1.19 to 2.01
1756-RN605	the changes from revision 2.01 to 2.02

These publications are available at www.rockwellautomation.com/literature



www.rockwellautomation.com

Power, Control and Information Solutions Headquarters

Americas: Rockwell Automation, 1201 South Second Street, Milwaukee, WI 53204-2496 USA, Tel: (1) 414.382.2000, Fax: (1) 414.382.4444
Europe/Middle East/Africa: Rockwell Automation, Vorstlaan/Boulevard du Souverain 36, 1170 Brussels, Belgium, Tel: (32) 2 663 0600, Fax: (32) 2 663 0640
Asia Pacific: Rockwell Automation, Level 14, Core E Cyberport 3, 100 Cyberport Road, Hong Kong, Tel: (852) 2887 4788, Fax: (852) 2508 1846

Publication 1756-RN626A-EN-P – January 2006

PN 957988-85

Copyright © 2006 Rockwell Automation. All rights reserved.