



S6/S6R DC ARMATURE SUPPLY
SEE SHEETS 4 FOR DETAILS.

POWER I/F PC BOARD

FIELD SUPPLY ASSEMBLY

-BASIC
SEE SHEET 6 & 9
-ENHANCED <19
SEE SHEET 7 & 9
-REGULATED <19
SEE SHEET 8 & 11

- NOTES:
- <1 FOR NOTE, SEE SHEET 1.
 - <2 FOR NOTE, SEE SHEET 1.
 - <3 FOR NOTE, SEE SHEET 1.
 - <5 FOR NOTE, SEE SHEET 1.
 - <6 FOR NOTE, SEE SHEET 5.
 - <7 FOR NOTE, SEE SHEET 5.
 - <8 FOR NOTE, SEE SHEET 1.
 - <16 FOR NOTE, SEE SHEET 1.
 - <18 FOR NOTE, SEE SHEET 1.
 - <19 FOR NOTE, SEE SHEET 1.

- ⊠ FASTON CONNECTOR
- TP TWISTED PAIR
- PX-X PLUG TERMINAL CONNECTION
- TERMINAL CONNECTION

SCHEMATIC FOR
20 THRU 30HP AT 230VAC
40 THRU 60HP AT 460VAC

REVISION 04		ECN 98R1210	
DATE 5-31-96		SCALE: NONE	
CK. MWQ		ENG'R JEB	
APP. TMC		DISTRIBUTION 850 -2	
DATE 1-29-99		BY: TLS	
Rockwell Automation			
WIRING DIAGRAM BULLETIN 1397 S6 / S6R 30 / 60HP 230 / 460VAC			
DR. TLS	DATE 5-31-96	SCALE: NONE	SHEET 2 OF 12
CK. MWQ	ENG'R JEB	DISTRIBUTION 850 -2	30371-23