

**1326DP Motor Parts
DC Servomotor for use with the 1388 Drive**

| <u>Catalog Number</u> | <u>Part Number</u> | <u>Description</u> |
|--|--------------------|-------------------------|
| <i>Motor Brushes:</i> (one brush per part number, 4 to 16 brushes are used on each motor) | | |
| ***** | 111875 | DP-A & DP-I Motors |
| ***** | 111876 | DP-C, DP-E, DP-S Motors |
| ***** | 111879 | DP-U Motors |
| ***** | 111880 | DP-W & DP-X Motors |
| ***** | 111878 | DP-M Motors |
| ***** | 111881 | DP-P Motors |

| | | |
|---|--------|-------------------|
| <i>Tachometer Brushes:</i> (one brush per part number, typically 4 required) | | |
| ***** | 111882 | All 1326DP motors |

Note: All other parts for the 1326DP motors can be obtained by calling Peerless-Winsmith at (330) 399-3651.

Note: All other parts for the 1326DP motors can be obtained by calling Peerless-Winsmith at (330) 399-3651.