

Speed Command from HIM mounted on Drive

Program:

**File C / Speed Command
Group - Speed Reference**

90 (Speed Ref A Sel) = 18 (DPI Port 1)