

Speed Command from HIM mounted on Drive

Program:

File - Speed Command

Group - Speed Reference

90 (Speed Ref A Sel) = 18 (DPI Port 1)